







www.arrowgear.com


2301 Curtiss Street • Downers Grove, IL 60515

• (630) 969-7640 • Fax: (630) 969-0253





IPRO 320 S07

Planning the implementation of a New ERP software platform



new user interfaces





Methodology

⇒ Seven Visits to Arrow Gear Company ⇒ Interviews with managers of different departments \Rightarrow Test the Visual Infor ERP software version 6.3.8 \Rightarrow Attend training sessions Visual Infor ERP software 6.5.2 \Rightarrow Learned the tutorial for Visual Infor ERP software 6.5.2 \Rightarrow Identified several issues in Visual Infor ERP software & interviews

Some major issues ⇒ Inefficient interfaces within Visual ERP system

- \Rightarrow Lack of communication between modules of the software
- ⇒ Lack of logging events and changes
- \Rightarrow No estimation times for processes to accurately schedule jobs

Recommendations

Several issues were solved by upgrade ⇒ Better Training on software modules \Rightarrow Take into account machine setup time \Rightarrow Check job histories



Engineering-Process and time standards.



